Auxiliary Contact Modules (for DILM7 – DILM32 Contactors) 128

Auxiliary	NO	NC NC	Schematic	For use with	Catalog Number	Price
Top Mount - Standard Terminal Markings						
	1	1	- 121 33 - 122 34	DILM7-10 — DILM32-10 O DILMP20 — DILMP45	DILM32-XHI11	
	0	2	L21 L31 -7- L22 L32		DILM32-XHI02	
0000	2	2	21 31 43 53 		DILM32-XHI22	
Top Mount - Alternative Terminal Markings						
	2	0	53 63 	DILM7 — DILM32 DILMP20 — DILMP45 DILA	DILA-XHI20	
	1	1	\\\\ 54\\ 62		DILA-XHI11	
	0	2	151 L61 -1- 152 162		DILA-XHIO2	
	1EM ⑤	1LB ⑤	-\frac{1^{57}}{58}\frac{65}{66}		DILA-XHIV11	
THE STATE OF THE S	4	0	-\frac{153}{54} \frac{63}{64} \frac{73}{74} \frac{83}{84}		DILA-XHI40	
	3	1	-\sqrt{53 62 74 84}		DILA-XHI31	
	2	2	-\frac{153}{54} \frac{161}{171} \frac{183}{183} -\frac{1}{54} \frac{162}{172} \frac{184}{84}		DILA-XHI22	
	1	3	-\frac{153\61\71\81}{54\62\72\82		DILA-XHI13	
	0	4			DILA-XHI04	
	1+ 1EM ⑤	1+ 1LB 5	-\frac{157}{7}\frac{165}{7}\frac{771}{7}\frac{1}{1}\frac{83}{7}\frac{7}{1}\frac{1}{2}\frac{83}{84}		DILA-XHIV22	
See Accessory Guide on page A33.						

- 1 DILM-7 DILM-32 contactors include a built-in one pole auxiliary contact.
- 2 Mechanically linked contacts with DILM7 DILM32 between the integrated auxiliary contact and auxiliary contact module, as well as within the auxiliary contact modules (except DILA-XHÍV11 early make/late break).
- Mirror contact with DILM7-01 − DILM32-01, as well as in combination with auxiliary contact modules.
- ◆ The 2 and 4-pole DILM32-XHI... auxiliary contact modules with terminal markings 21/22 cannot be used with DILM...-01 contactors. Use Top Mount DILA-XHI... with Alternative Terminal Markings instead.
- **⑤** EM = Early Make LB = Late Break